App Number 09/690,657 (Thompson); Art Unit 3635, Examiner: Mark R. Wendell

## **RESPONSE**

- 1. A new set of drawings should be submitted. The applicant has enclosed a clean set of new drawings. This application is a divisional of application # 09/032,560, now U.S. Patent # 6,131,354.
- 2. Figures 27 and 29 appear in the drawings, but not in the brief description. The figure numbers and brief description, on the original application that the examiner has, were changed for the issued patent. It may be preferable to use the brief description on page 43 of U.S. Patent # 6,131,354 for this application.
- 3. Figures 27E, 29C, and 37B are in the brief description, but not in the drawings. Hopefully, the issued patent has the correct drawing numbers and brief description.
- 4. Two Figure 38's exist within the drawings. The applicant believes that this issue was corrected in U.S. Patent # 6,131,354.

Very Respectfully,

Thomas C. Thompson 92-543 Kokole Pl. Makakilo, Hi 96707 (808) 672-3107